

NHDOT Redlist Summary

Bridge Data --> Insp Date FSR Owner Type Width Length Spans Weight VC over/under Year Built
Road Data --> AADT, Year Status Width Functional Class NH System / Class & Rebuilt

Redlist Note

Acworth

0010

113/064	NH123A	over	BOWERS BROOK	Nov 2010	47.4	NHDOT	Jack	27.3	17	1	E2	Y	1915
		State Redlist	Not Applicable	Over			360, 2008	24.0	Rural Min. Collector		Primary-DOT Maintained		
		Serious Condition. Additional damage during 2005 flood event. Was listed in program for 2007, \$600,000.00. Temporary flood repairs done by Bridge Maintenance.				Replace	In the Program			\$1,000,000.00		2018	

Alstead

0050

073/163	NH123A	over	WARREN BROOK	Nov 2010	61.5	NHDOT	CTB	29.1	34	1	Fed Br	C1	Y	1935
			State Redlist	Structurally Deficient	Over	1100, 2008		26.7	Rural Min. Collector		Primary-DOT Maintained			
			Deck Poor. Additional damage during 2005 flood.			Rehab	To be addressed by Bridge Maintenance			WTP				

Andover

0080

050/093	NH 11	over	BLACKWATER RIVER	Oct 2010	70.0	NHDOT	IB-C	48.5	124	2	Fed Br	NPR	Y	1959
			State Redlist	Structurally Deficient	Over		4800, 2009	46.0	Rural Minor Arterial		Primary-DOT Maintained			
			Deck Poor. Pier repaired 2005 by Bridge Maintenance. Scour Critical			Rehab	In the Program			\$2,555,000.00	2012			
179/146	VALLEY ROAD	over	NHRR(ABD)	Oct 2010	67.1	NHDOT	TB	16.5	90	5	Fed Br	15	Y	23.17 1930, 2002
			State Redlist	Not Deficient	Over		40, 2005	15.2	Rural Local		Municipal Highway			
			Low Capacity, Posted 'Weight Limit 15 Tons'. Bridge Maintenance rehab completed 2002.				Monitor and Keep in Service							

Ashland

0110

107/094	US 3,NH 25	over	OWL BROOK	Nov 2010	49.7	NHDOT	IB-C	43.5	64	1	Fed Br	NPR	Y	1958
			State Redlist	Structurally Deficient	Over		3700, 2009	40.0	Rural Mjr. Collector		Primary-DOT Maintained			
		Deck Poor.			Rehab		Needs to be added to the Program				\$1,200,000.00			

NHDOT Redlist Summary

Bridge Data --> Insp Date FSR Owner Type Width Length Spans Weight VC over/under Year Built
Road Data --> AADT, Year Status Width Functional Class NH System / Class & Rebuilt

Redlist Note

Bedford

0190

090/065	NH101	over	PULPIT BROOK	Aug 2010 *	49.9	NHDOT	CP	.0	13	2	NPR	Y	1936
			State Redlist	Not Applicable	Over	NHS	18000, 2008	40.0	Rural Princ. Arterial	Primary-DOT Maintained			
			Settlement of concrete pipes, gaps between segments.			Replace	Needs to be added to the			\$600,000.00			
			Temporary repairs scheduled by Bridge Maintenance in 2011.				Program						

151/151	NH114	over	BOWMAN BROOK	Nov 2010 *	54.0	NHDOT	MP	.0	10	1	NPR	Y	1964
			State Redlist	Not Applicable	Over	NHS	21000, 2008	45.3	Urban Principal Arterial	Primary-DOT Maintained			
			Culvert Serious.			Rehab	Needs to be added to the			\$400,000.00			
							Program						

189/121	US 3	over	FEE TPK	Nov 2010	10.6	Turnpike Bureau, NHDOT	IB-C	41.5	150	2	Fed Br	NPR	Y	16.50	1955
			State Redlist	Structurally Deficient	Over	NHS	17000, 2008	30.0	Urban Expressway	Primary-DOT Maintained					
					Road Under	NHS	48897, 2008	55.8	Urban Expressway	Primary-Turnpike Maint.					
			Deck and Substructure Poor.			Replace	In the Program			\$13,975,000.00	2013				

Bennington

0210

093/094	BMRR(ABD)	over	ANTRIM ROAD	Nov 2010	N/A	NHDOT	TB	9.8	19	1	NPR	Y	13.42	1930
			State Redlist	Not Applicable	Road Under		3400, 2008	16.4	Rural Local	Municipal Highway				
			Rail line not in service, Severe Overheight Damage, Poor Condition.			Rehab	To be addressed by Rail and Transit			WTP				

Bow

0270

135/160	I-93,FEE TPK SB	over	I-89,TURKEY RIVER	Nov 2010	8.6	Turnpike Bureau, NHDOT	IB-C	35.8	244	5	Fed Br	NPR	Y	18.44	1957, 1980
			State Redlist	Structurally Deficient	Over	NHS	34400, 2008	30.0	Urban Interstate	Interstate (Turnpike)					
					Road Under	NHS	40000, 2003	-3.3	Urban Interstate	Interstate Highway					
			Deck and Substructure Poor.			Replace	In the Program			\$6,755,000.00	2011				

136/160	I-93,FEE TPK NB	over	I-89,TURKEY RIVER	Nov 2010	25.6	Turnpike Bureau, NHDOT	IB-C	47.8	244	5	Fed Br	NPR	Y	16.40	1957, 1980
			State Redlist	Structurally Deficient	Over	NHS	36000, 2009	42.0	Urban Interstate	Interstate (Turnpike)					
					Road Under	NHS	17000, 2004	60.0	Urban Interstate	Interstate Highway					
			Deck and Substructure Poor.			Replace	In the Program			\$6,755,000.00	2011				

NHDOT Redlist Summary

Bridge Data --> Insp Date	FSR	Owner	Type	Width	Length	Spans	Weight	VC over/under	Year Built
Road Data -->		Action	AADT, Year Status	Width	Functional Class	NH System / Class	& Rebuilt		

Redlist Note

Canaan

0360

124/103	CANAAN STREET	over	MASCOMA RIVER	Nov 2010	56.0	NHDOT	CRF	31.0	38	1	Fed Br	NPR Y	1936
	State Redlist		Structurally Deficient	Over			820, 2008	27.4	Rural Min. Collector			Secondary-DOT Maintained	
	Poor Condition.					Rehab	To be addressed by Bridge Maintenance					2015	

Center Harbor

0400

080/040	WAUKEWAN ROAD	over	LAKE WAUKEWAN INLET	Nov 2010	45.5	NHDOT	CS	21.2	13	1		NPR Y	1928
	State Redlist		Not Applicable	Over			390, 2008	19.0	Rural Min. Collector			Secondary-DOT Maintained	
	Poor Condition.					Replace	Needs to be added to the Program				\$1,000,000.00		

Chichester

0460

130/100	MAIN STREET	over	SANDERS BROOK	Nov 2010	38.0	NHDOT	Jack	33.8	15	1		E2 Y	1931
	State Redlist		Not Applicable	Over			9000, 2007	30.4	Rural Local			Secondary-DOT Maintained	
	Poor Condition.					Rehab	To be addressed by Bridge Maintenance					WTP	

Concord

0520

136/117	I-93,US 4 NB	over	MERRIMACK RIVER	Nov 2010	56.7	NHDOT	DPG	61.8	526	3	Fed Br	NPR Y	1959, 1988
	State Redlist		Structurally Deficient	Over		NHS	24000, 2008	51.0	Urban Interstate			Interstate Highway	
	Repaired fracture in floorbeam.		Scour Critical.			Rehab	Needs to be added to the Program				\$500,000.00		
142/116	DELTA DRIVE	over	I-93,US 4	Nov 2010	62.1	NHDOT	IB-C	38.6	192	4	Fed Br	NPR Y	16.14 1958
	State Redlist		Structurally Deficient	Over			1100, 2008	28.0	Urban Local			Compact Highway	
				Road Under		NHS	48000, 2008	-3.3	Urban Interstate			Interstate Highway	
	Deck Poor.					Rehab	In the Program				\$3,898,446.00	2012	

NHDOT Redlist Summary

Bridge Data --> Insp Date FSR Owner Type Width Length Spans Weight VC over/under Year Built
Road Data --> AADT, Year Status Width Functional Class NH System / Class & Rebuilt

Redlist Note

Concord

0520

203/087	NH 3A over I-93,FEE TPK	Nov 2010	42.2	Turnpike Bureau, NHDOT	IB-C	63.5	217	4	Fed Br	NPR Y	15.96	1957
	State Redlist	Structurally Deficient	Over			15000, 2009	52.0	Urban Minor Arterial	Secondary-Compact Maint.			
			Road Under	NHS		68800, 2008	-3.3	Urban Interstate	Interstate (Turnpike)			
	Deck and Substructure Poor.			Replace		In the Program			\$5,043,547.00	2012		

Conway

0540

158/137	US302,NH113 over CONWAY LAKE OUTLET	Feb 2011	25.6	NHDOT	CTB	33.0	106	3	Fed Br	NPR Y		1955
	State Redlist	Structurally Deficient	Over	NHS		11000, 2007	27.0	Rural Princ. Arterial	Primary-DOT Maintained			
	Deck Poor. Bridge Maintenance installed temporary railing 2010.			Replace		In the Program			\$3,461,500.00	2012		

167/067	EAST SIDE ROAD over SACO RIVER	Sep 2010	15.8	NHDOT	TB-C	18.8	227	2	Fed Br	03 Y	10.42	1890, 1989
Saco River Covered Br.	State Redlist	Structurally Deficient	Over			2400, 1992	18.1	Rural Min. Collector	Secondary-DOT Maintained			
	Covered Bridge, Posted 'Weight Limit 3 Tons'. Fire supression installation, 2002. Scour Critical. Seeking Covered Bridge Preservation Funds.					Monitor and Keep in Service						

Cornish

0550

064/108	CORNISH TOLL BR RD over CONNECTICUT RIVER	Nov 2010	5.0	NHDOT	TB-C	20.7	449	2	Fed Br	10 Y	9.42	1866, 1989
Cornish Windsor Covered	State Redlist	Structurally Deficient	Over			2900, 2009	19.5	Rural Mjr. Collector	Secondary-DOT Maintained			
	Covered Bridge, Posted 'Weight Limit 10 Tons'. Fire supression installation, 2002. Deck work completed 2007 by Bridge Maintenance. Scour Critical. Seeking Covered Bridge Preservation Funds.					Monitor and Keep in Service						

Deerfield

0600

137/116	NH107 over FREESE'S POND	Nov 2010 *	72.1	NHDOT	MP	.0	13	1		NPR Y		1973
	State Redlist	Not Applicable	Over			3000, 2004	32.0	Rural Mjr. Collector	Secondary-DOT Maintained			
	Poor Condition.			Replace		Needs to be added to the Program			\$800,000.00			

NHDOT Redlist Summary

Bridge Data --> Insp Date FSR Owner Type Width Length Spans Weight VC over/under Year Built
Road Data --> AADT, Year Status Width Functional Class NH System / Class & Rebuilt

Redlist Note

Dover

0650

109/106	NH 9	over	BMRR	Nov 2010	33.7	NHDOT	IB-C	31.1	75	2	Fed Br	NPR Y	17.25	1935
		State Redlist		Structurally Deficient	Over			9900, 2005	24.0	Urban Minor Arterial		Primary-DOT Maintained		
		Deck Poor. CWIP. Temporary bridge in place.				Replace	In the Program			\$6,832,023.00		2009		
182/123	GULF ROAD	over	SALMON FALLS RIVER	Nov 2010	24.5	NHDOT	IB-C	32.1	489	27	Fed Br	NPR Y		1982
		State Redlist		Structurally Deficient	Over			5000, 2006	29.5	Urban Collector		Secondary-DOT Maintained		
		Substructure Poor, Scour Critical.				Rehab	Needs to be added to the Program			\$13,000,000.00				
200/023	ROAD	over	LITTLE BAY	Nov 2010 *	31.0	Turnpike Bureau, NHDOT	HT	30.6	1585	9	Fed Br	BRC Y	18.00	1934, 1950
General Sullivan Bridge		State Redlist		Structurally Deficient	Over			0, 2003	24.0	Urban Local		Turnpike, not Primary		
		Critical Condition. Limited capacity for pedestrian loading. Newington - Dover project under design and Construction.				Rehab	In the Program			\$31,977,000.00		2015		

Durham

0700

093/080	BENNETT ROAD	over	BMRR	Nov 2010	44.9	NHDOT	TB	21.5	33	1	Fed Br	10 Y	18.01	1910, 2003
		State Redlist		Not Deficient	Over			610, 2006	20.2	Rural Local		Municipal Highway		
		Low Capacity, Posted 'Weight Limit 10 Tons'. Rehab by Bridge Maintenance, 2002.					Waiting Municipal Action							

East Kingston

0710

061/064	NH107A	over	BMRR, ROAD	Nov 2010	45.3	NHDOT	IB-C	32.2	123	3	Fed Br	E2 Y	18.42	1937
		State Redlist		Structurally Deficient	Over			5700, 2008	28.0	Rural Min. Collector		Secondary-DOT Maintained		
		Deck Poor.				Replace	Needs to be added to the Program			\$4,000,000.00				

Effingham

0740

167/095	NH153	over	SOUTH RIVER	Nov 2010	43.3	NHDOT	CRF	27.4	16	1		E2 Y		1924
		State Redlist		Not Applicable	Over			660, 2009	24.0	Rural Min. Collector		Secondary-DOT Maintained		
		Poor Condition.				Replace	To be addressed by Bridge Maintenance					2013		

NHDOT Redlist Summary

Bridge Data --> Insp Date	FSR	Owner	Type	Width	Length	Spans	Weight	VC over/under	Year Built
Road Data -->		Action	AADT, Year Status	Width	Functional Class	NH System / Class	& Rebuilt		

Redlist Note

Errol

0800

071/030	NH 16	over	OUTLET MOOSE POND	Oct 2010	11.5	NHDOT	IB-C	28.5	12	1	C2	Y	1931
			State Redlist	Not Applicable	Over		1200, 2009	25.6	Rural Mjr. Collector		Primary-DOT Maintained		
			Substructure in Serious Condition.			Replace	To be addressed by Bridge Maintenance				2013		

Exeter

0820

057/052	NH111	over	EXETER RIVER	Nov 2010	67.3	NHDOT	IB-C	36.0	38	1	Fed Br	NPR	Y	1933, 1986
			State Redlist	Structurally Deficient	Over		8000, 2009	32.4	Rural Mjr. Collector		Secondary-DOT Maintained			
			Abutment Undermined.			Rehab	To be addressed by Bridge Maintenance				2011			

088/076	PARK STREET	over	BMRR	Nov 2010	46.6	NHDOT	LT	26.6	63	1	Fed Br	10	Y	17.65 1900, 2004
			State Redlist	Not Deficient	Over		590, 2006	17.4	Urban Local		Compact Highway			
			Low Capacity, Posted 'Weight Limit 10 Tons'. Bridge Maintenance replaced floor and several steel members, 2002, 2003.				Waiting Municipal Action							

Farmington

0840

096/140	NH153	over	COCHECO RIVER	Nov 2010	11.3	NHDOT	IB-C	40.5	48	2	Fed Br	NPR	Y	1924
			State Redlist	Structurally Deficient	Over		7900, 2006	27.4	Rural Min. Collector		Secondary-DOT Maintained			
			Poor Condition. Scour Critical.			Replace	In the Program				\$1,800,000.00	2014		

Francestown

0860

079/089	NH136	over	BEAVER DAM BROOK	Nov 2010 *	62.6	NHDOT	CS	.0	10	1	E1	Y	1926, 1980
			State Redlist	Not Applicable	Over		1400, 2009	32.0	Rural Mjr. Collector		Secondary-DOT Maintained		
			Culvert Poor. Concrete Slab and Steel Pipe.			Rehab	To be addressed by Bridge Maintenance				WTP		

NHDOT Redlist Summary

Bridge Data --> Insp Date	FSR	Owner	Type	Width	Length	Spans	Weight	VC over/under	Year Built
Road Data -->		Action	AADT, Year Status	Width	Functional Class	NH System / Class	Year		& Rebuilt

Redlist Note

Franconia

0870

070/115	NH 18	over	GALE RIVER	Sep 2010	30.2	NHDOT	TPG	28.0	58	1	Fed Br	15	Y	1930
			State Redlist	Structurally Deficient	Over		570, 2008	25.0	Rural Min. Collector		Primary-DOT Maintained			
			Low Capacity, Posted 'Weight Limit 15 Tons'.			Rehab	To be addressed by Bridge Maintenance				2011			

089/099	NH 18	over	LAFAYETTE BROOK	Oct 2010	41.0	NHDOT	CTB	29.2	56	1	Fed Br	E2	Y	1932
			State Redlist	Structurally Deficient	Over		570, 2009	23.9	Rural Min. Collector		Primary-DOT Maintained			
			Superstructure Poor.			Rehab	To be addressed by Bridge Maintenance				WTP			

Franklin

0880

162/100	NHRR(ABD)	over	NH127	Oct 2010	N/A	NHDOT	TPG	12.0	72	1	Fed Br	NPR	Y	13.81 1928
			State Redlist	Not Applicable	Road Under		2000, 2007	39.4	Rural Mjr. Collector		Secondary-DOT Maintained			
			Deck holed, Abutments Poor.			Remove	Needs to be added to the Program				\$750,000.00			

Gilford

0910

160/053	US 3,NH 11 BYPASS	over	NH 11A	Nov 2010	54.7	NHDOT	IB-C	49.8	81	1	Fed Br	NPR	Y	14.14 1965
			State Redlist	Structurally Deficient	Over	NHS	12000, 2008	44.0	Rural Princ. Arterial		Primary-DOT Maintained			
			Deck Serious.			Rehab	In the Program				\$1,700,000.00	2012		

Hampton Falls

1100

162/044	NH 84	over	HAMPTON FALLS RIVER	Nov 2010 *	53.8	NHDOT	MP	.0	10	1		NPR	Y	1961
			State Redlist	Not Applicable	Over		3300, 2009	27.4	Rural Local		Secondary-DOT Maintained			
			Poor Condition.			Rehab	To be addressed by Bridge Maintenance				2011			

NHDOT Redlist Summary

Bridge Data --> Insp Date FSR Owner Type Width Length Spans Weight VC over/under Year Built
Road Data --> AADT, Year Status Width Functional Class NH System / Class & Rebuilt

Redlist Note

Hampton

1110

235/025	NH 1A over HAMPTON RIVER	Nov 2010	26.3	NHDOT		BAS	33.5	1199	13	Fed Br	E2	Y		1949, 1984
Neil R. Underwood Mem.	State Redlist	Structurally Deficient	Over		9239, 2007		26.0	Rural Minor Arterial		Secondary-DOT Maintained				
	Superstructure Poor. Mechanical and electrical repairs 2001, 2002, and 2003. Current Project: \$5,382,000.00 for rehab, \$3,750,000.00 for painting. CWIP, Scour Critical			Rehab	In the Program					\$9,130,000.00	2009			

Hancock

1120

158/068	FORREST ROAD over CONTOOCOOK RIVER	Nov 2010	37.1	NHDOT		TB-C	26.0	88	1	Fed Br	08	Y	12.50	1937
County Bridge	State Redlist	Structurally Deficient	Over		960, 2007		20.1	Rural Mjr. Collector		Secondary-DOT Maintained				
	Covered Bridge, Posted 'Weight Limit 8 Tons'. Fire supression installation, 2002.				Monitor and Keep in Service									

Harrisville

1150

056/058	CHESHAM ROAD over MINNEWAWA BROOK	Nov 2010	49.8	NHDOT		CS	27.0	90	3	Fed Br	NPR	Y		1939
	State Redlist	Structurally Deficient	Over		1100, 2008		24.0	Rural Min. Collector		Secondary-DOT Maintained				
	Slab Poor.			Rehab	To be addressed by Bridge Maintenance					WTP				

Haverhill

1170

215/158	MILL STREET over NHRR(ABD)	Sep 2010	17.0	NHDOT		TB	18.8	147	7	Fed Br	06	Y		1940
	State Redlist	Structurally Deficient	Over		160, 2008		16.6	Rural Local		Municipal Highway				
	Poor Condition, Low Capacity, Posted 'Weight Limit 6 Tons'. Bridge maintenance looking at rehab. Had been programmed for 2005.			Remove	Waiting Municipal Action									

Jackson

1320

148/050	NH 16A over ELLIS RIVER	Sep 2010	21.4	NHDOT		TB-C	25.8	121	1	Fed Br	03P	Y	9.55	1876, 2004
Honeymoon Covered Bridge	State Redlist	Not Deficient	Over		2200, 2008		15.7	Rural Min. Collector		Secondary-DOT Maintained				
	Covered Bridge, Posted 'Weight Limit 3 Tons'. Rehab 2004.				Monitor and Keep in Service									

NHDOT Redlist Summary

Bridge Data --> Insp Date	FSR	Owner	Type	Width	Length	Spans	Weight	VC over/under	Year Built
Road Data -->		Action	AADT, Year Status	Width	Functional Class	NH System / Class	& Rebuilt		

Redlist Note

Jefferson

1350

046/178	US 2 over	ISRAEL RIVER	Sep 2010	40.6	NHDOT	IB-C	46.6	164	2	Fed Br	NPR Y	1974
	State Redlist	Structurally Deficient	Over		NHS	3500, 2009	42.5	Rural Princ. Arterial		Primary-DOT Maintained		
	Deck and Substructure Poor.				Rehab	In the Program				\$2,710,000.00	2014	

Keene

1360

129/099	NH 9,NH 10 over	ELM STREET	Nov 2010	68.5	NHDOT	IB-C	52.9	76	1	Fed Br	NPR Y	14.70 1978
	State Redlist	Structurally Deficient	Over		NHS	9700, 2009	48.8	Urban Principal Arterial		Primary-DOT Maintained		
	Deck Poor.				Rehab	In the Program				\$1,900,000.00	2016	

Laconia

1390

126/163	CENTENARY AVENUE over	NHRR	Nov 2010	2.0	NHDOT	TB	22.6	121	7	Fed Br	07 Y	17.75 1940
	State Redlist	Structurally Deficient	Over			230, 2006	16.5	Rural Local		Municipal Highway		
	Low Capacity, Serious Condition. Posted 'Weight Limit 7 Tons'.					Monitor and Keep in Service						
131/154	US 3 over	NHRR	Nov 2010	32.7	NHDOT	CS	35.3	32	1	Fed Br	E1 Y	20.70 1933
	State Redlist	Structurally Deficient	Over		NHS	8400, 2008	27.0	Urban Principal Arterial		Primary-DOT Maintained		
	Poor Condition.				Rehab	In the Program				\$1,660,000.00	2015	

Landaff

1420

137/031	NH116 over	DAVIS BROOK	Sep 2010 *	55.4	NHDOT	MP	.0	11	1		NPR Y	1961
	State Redlist	Not Applicable	Over			370, 2009	31.0	Rural Min. Collector		Secondary-DOT Maintained		
	Serious Condition.				Rehab	To be addressed by Bridge Maintenance				2011		

Lebanon

058/127	US 4	over	CONNECTICUT RIVER		Nov 2010	0.0	NHDOT	BAIB	26.0	392	3	Fed Br	NPR	Y	13.78	1936, 1976
			State Redlist	Structurally Deficient	Over			14000, 2005	24.0	Urban Minor Arterial		Secondary-Compact Maint.				
			Deck and Superstructure Serious. Bridge Maintenance Steel Repairs 2005. NH Recovery Project to install Temporary Bridge 2009, \$3339864.39			Replace	In the Program		\$14,464,864.00	2012						
093/109	I-89 NB	over	US 4		Nov 2010	62.6	NHDOT	IB-C	61.3	115	1	Fed Br	NPR	Y	16.31	1966
			State Redlist	Structurally Deficient	Over		NHS	16500, 2007	55.5	Urban Interstate		Interstate Highway				
					Road Under			34000, 1994	-3.3	Urban Minor Arterial		Primary-Compact Maint.				
			Deck Poor.				Rehab	In the Program		\$3,207,522.00	2013					
155/117	I-89 SB	over	HARDY HILL ROAD		Nov 2010	61.9	NHDOT	IB-C	42.3	45	1	Fed Br	NPR	Y	17.45	1966, 1975
			State Redlist	Structurally Deficient	Over		NHS	14000, 2007	38.0	Rural Interstate		Interstate Highway				
			Deck Poor.			Rehab	In the Program		\$2,000,000.00	2012						
156/117	I-89 NB	over	HARDY HILL ROAD		Nov 2010	60.8	NHDOT	IB-C	42.3	45	1	Fed Br	NPR	Y	13.86	1966
			State Redlist	Structurally Deficient	Over		NHS	14000, 2007	38.0	Rural Interstate		Interstate Highway				
			Deck Poor.			Rehab	In the Program		\$2,000,000.00	2012						
158/114	I-89 SB	over	NHRR(ABD)		Nov 2010	66.0	NHDOT	IB-C	42.0	147	3	Fed Br	NPR	Y		1966, 1987
			State Redlist	Structurally Deficient	Over		NHS	14000, 2007	38.0	Rural Interstate		Interstate Highway				
			Deck Poor.			Rehab	In the Program		\$3,000,000.00	2014						
188/126	US 4	over	NHRR(ABD),MASCOMA RIVER		Nov 2010	34.7	NHDOT	DPG	31.0	463	6	Fed Br	E2	Y		1930, 1957
			State Redlist	Structurally Deficient	Over			13000, 2007	26.0	Rural Minor Arterial		Primary-DOT Maintained				
			Deck and Floorbeams Poor. Scour Critical.			Replace	In the Program		\$10,900,000.00	2012						
192/129	PAYNE ROAD	over	NHRR(ABD)		Nov 2010	88.5	NHDOT	TB	18.0	54	2	Fed Br	15	Y		1946, 2004
			State Redlist	Not Deficient	Over			230, 2007	16.0	Rural Local		Secondary-DOT Maintained				
			Low Capacity, Posted 'Weight Limit 15 Tons'.				Monitor and Keep in Service									

NHDOT Redlist Summary

Bridge Data --> Insp Date FSR Owner Type Width Length Spans Weight VC over/under Year Built
Road Data --> AADT, Year Status Width Functional Class NH System / Class & Rebuilt

Redlist Note

Lee

1450

106/126	US 4	over	OYSTER RIVER	Jul 2010	62.9	NHDOT	CRF	48.0	24	1	Fed Br	NPR Y	1929, 1968
			State Redlist	Structurally Deficient	Over	NHS	17000, 2006	46.5	Rural Princ. Arterial			Primary-DOT Maintained	
			Poor Condition.			Replace	Needs to be added to the Program				\$1,000,000.00		

Lincoln

1480

149/110	FLUME BUS ROUTE	over	PEMIGEWASSET RIVER	Nov 2010	43.3	NHDRED	TB-C	16.3	52	1	Fed Br	15 Y	7.84	1886
	Flume Covered Bridge		State Redlist	Structurally Deficient	Over		50, 2000	16.2	Rural Local			Undetermined / NA		
			Covered Bridge, Low Capacity (Flume Bus use Only).				Monitor and Keep in Service							

202/100	I-93 NB OFF RAMP	over	CLARKS RR, PEMIGEWASSET R	Oct 2010	73.5	NHDOT	IB-C	30.8	253	2	Fed Br	NPR Y	17.80	1973
			State Redlist	Structurally Deficient	Over	NHS	1800, 1984	26.5	Rural Interstate			Interstate Highway		
			Deck Poor. Scour Critical.			Rehab	Needs to be added to the Program				\$1,000,000.00			

Littleton

1530

105/135	I-93 NB	over	CONNECTICUT RIVER	Sep 2010	62.1	NHDOT	IB-C	44.8	670	4	Fed Br	NPR Y	1976
	Sen. Andrew Poulsen Br.		State Redlist	Structurally Deficient	Over	NHS	2950, 2009	40.5	Rural Interstate			Interstate Highway	
			Deck Poor. Scour Critical.			Rehab	In the Program				\$6,000,000.00	2012	

200/137	NH135	over	COW BROOK	Sep 2010 *	50.1	NHDOT	MP	.0	10	1		NPR Y	1973
			State Redlist	Not Applicable	Over		3100, 2007	32.2	Rural Min. Collector			Secondary-DOT Maintained	
			Culvert Serious.			Rehab	To be addressed by Bridge Maintenance					2011	

223/057	NH116	over	PALMER BROOK	Sep 2010 *	45.4	NHDOT	MP	.0	20	2		NPR Y	1900
			State Redlist	Not Applicable	Over		6300, 2007	45.0	Rural Mjr. Collector			Secondary-DOT Maintained	
			Culvert Serious.			Rehab	To be addressed by Bridge Maintenance					2012	

NHDOT Redlist Summary

Bridge Data --> Insp Date FSR Owner Type Width Length Spans Weight VC over/under Year Built
Road Data --> AADT, Year Status Width Functional Class NH System / Class & Rebuilt

Redlist Note

Londonderry

1540

096/163	I-93 SB	over	BMRR(ABD)	Nov 2010	28.0	NHDOT	IB-C	47.8	142	3	Fed Br	NPR Y	20.58	1962
			State Redlist	Structurally Deficient	Over	NHS	37500, 2006	42.0	Rural Interstate		Interstate Highway			
			Deck Serious.			Replace	In the Program				\$9,293,933.00	2013		
097/163	I-93 NB	over	BMRR(ABD)	Nov 2010	34.0	NHDOT	IB-C	51.8	150	3	Fed Br	NPR Y	21.08	1962
			State Redlist	Structurally Deficient	Over	NHS	37500, 2006	46.0	Rural Interstate		Interstate Highway			
			Deck and Substructure Serious.			Replace	In the Program				\$9,293,933.00	2013		
099/160	I-93 SB	over	NH 28	Nov 2010	43.0	NHDOT	IB-C	43.8	153	3	Fed Br	NPR Y	16.25	1962
			State Redlist	Structurally Deficient	Over	NHS	37500, 2006	38.0	Rural Interstate		Interstate Highway			
			Deck Serious.			Replace	In the Program				\$9,293,933.00	2013		
100/160	I-93 NB	over	NH 28	Nov 2010	43.0	NHDOT	IB-C	43.8	150	3	Fed Br	NPR Y	16.27	1962
			State Redlist	Structurally Deficient	Over	NHS	37500, 2006	38.0	Rural Interstate		Interstate Highway			
			Deck Serious.			Replace	In the Program				\$9,293,933.00	2013		

Manchester

1610

059/087	I-93 NB	over	RD,BMRR,MERRIMACK RIVER	Nov 2010	62.1	NHDOT	IB-C	68.8	826	4	Fed Br	NPR Y	23.29	1976
			State Redlist	Structurally Deficient	Over	NHS	32650, 2008	64.5	Urban Interstate		Interstate Highway			
			Deck Poor.			Rehab	In the Program				\$7,008,583.00	2010		
060/086	I-93 SB	over	RD,BMRR,MERRIMACK RIVER	Nov 2010	61.6	NHDOT	IB-C	68.8	826	4	Fed Br	NPR Y	23.29	1976
			State Redlist	Structurally Deficient	Over	NHS	32650, 2008	64.5	Urban Interstate		Interstate Highway			
			Deck Poor.			Rehab	In the Program				\$7,008,583.00	2010		
111/066	SOUTH RAMP(RAMP K)	over	I-293,FEE TPK	Nov 2010	45.9	Turnpike Bureau, NHDOT	IB-C	37.5	104	2	Fed Br	NPR Y	16.08	1957
			State Redlist	Structurally Deficient	Over		17000, 1994	31.0	Urban Local		Interstate (Turnpike)			
				Road Under		NHS	55600, 2008	-3.3	Urban Interstate		Interstate (Turnpike)			
			Substructure Poor.			Rehab	To be addressed by Bridge Maintenance					2011		
144/066	I-293,FEE TPK	over	N BR PISCATAQUOG RIVER	Nov 2010	29.6	Turnpike Bureau, NHDOT	IB-C	84.9	148	3	Fed Br	NPR Y		1957
			State Redlist	Structurally Deficient	Over	NHS	35600, 2008	72.0	Urban Interstate		Interstate (Turnpike)			
			Deck and Substructure Poor.			Rehab	In the Program				\$9,034,750.00	2014		

NHDOT Redlist Summary

Bridge Data --> Insp Date FSR Owner Type Width Length Spans Weight VC over/under Year Built
Road Data --> AADT, Year Status Width Functional Class NH System / Class & Rebuilt

Redlist Note

Manchester

1610

146/064	I-293,FEE TPK	over	S BR PISCATAQUOG RIVER	Nov 2010	42.6	Turnpike Bureau, NHDOT	IB-C	69.8	213	3	Fed Br	NPR Y	1957
	State Redlist		Structurally Deficient	Over		NHS 34000, 2009		60.0	Urban Interstate		Interstate (Turnpike)		
	Deck Poor.					Rehab	In the Program				\$9,034,750.00	2014	
146/065	I-293,FEE TPK SPUR	over	S BR PISCATAQUOG RIVER	Nov 2010	43.6	Turnpike Bureau, NHDOT	IB-C	25.8	216	3	Fed Br	NPR Y	1957
	State Redlist		Structurally Deficient	Over		NHS 34000, 2009		20.0	Urban Interstate		Interstate (Turnpike)		
	Deck Poor.					Rehab	In the Program				\$9,034,750.00	2014	
149/063	I-293,FEE TPK	over	SPUR D	Nov 2010	41.6	Turnpike Bureau, NHDOT	IB-C	73.8	149	3	Fed Br	NPR Y	16.42 1957
	State Redlist		Structurally Deficient	Over		NHS 68000, 2009		62.0	Urban Interstate		Interstate (Turnpike)		
				Road Under		NHS 6000, 1992		-3.3	Urban Interstate		Interstate (Turnpike)		
	Deck Poor.					Rehab	In the Program				\$9,034,750.00	2014	
153/061	I-293 RAMP	over	I-293,FEE TPK	Nov 2010	44.3	Turnpike Bureau, NHDOT	IB-C	25.8	252	4	Fed Br	NPR Y	16.08 1956
	State Redlist		Structurally Deficient	Over		NHS 67000, 2003		20.0	Urban Interstate		Interstate (Turnpike)		
				Road Under		NHS 71200, 2008		-3.3	Urban Interstate		Interstate (Turnpike)		
	Deck Poor.					Replace	In the Program				\$2,500,000.00	2011	

Meredith

1670

131/105	MEREDITH CENTER RD	over	OUTLET WICKWAS POND	Nov 2010	53.4	NHDOT	IB-C	33.7	63	1	Fed Br	E2 Y	1937
	State Redlist		Structurally Deficient	Over		4000, 2009		29.0	Rural Mjr. Collector		Secondary-DOT Maintained		
	Deck Poor.					Rehab	Needs to be added to the Program				\$750,000.00		
134/092	MEREDITH CENTER RD	over	PICKEREL POND BROOK	Nov 2010 *	66.9	NHDOT	CB	20.0	11	1		NPR Y	1936
	State Redlist		Not Applicable	Over		3300, 2007		26.0	Rural Min. Collector		Secondary-DOT Maintained		
	Culvert Poor.					Replace	To be addressed by Bridge Maintenance					2011	

Merrimack

1680

111/115	FEE TPK	over	SOUHEGAN RIVER	Nov 2010	31.6	Turnpike Bureau, NHDOT	IB-C	92.5	229	3	Fed Br	NPR Y	1953
Merrill's Marauders Br.	State Redlist		Structurally Deficient	Over		NHS 54900, 2009		91.5	Rural Princ. Arterial		Primary-Turnpike Maint.		
	Deck and Substructure Poor.		CWIP.			Rehab	In the Program				\$15,499,331.00	2008	

NHDOT Redlist Summary

Bridge Data --> Insp Date FSR Owner Type Width Length Spans Weight VC over/under Year Built
Road Data --> AADT, Year Status Width Functional Class NH System / Class & Rebuilt

Redlist Note

Milton

1730

212/128	NH125	over	NHNCRR	Nov 2010	61.8	NHDOT	IB-C	34.6	153	3	Fed Br	NPR Y	18.47	1954
State Redlist				Structurally Deficient	Over		5300, 2008	28.0	Rural Mjr. Collector		Primary-DOT Maintained			
Deck Poor. Bid October 2010						Rehab	In the Program				\$1,588,746.00		2011	

Moultonborough

1760

140/251	NH109	over	BERRY POND BROOK	Nov 2010	60.9	NHDOT	CS	26.3	17	1		E1 Y		1927
State Redlist				Not Applicable	Over		780, 2009	24.0	Rural Local		Secondary-DOT Maintained			
Slab Poor.						Rehab	To be addressed by Bridge Maintenance				2012			
186/193	NH109	over	SHANNON BROOK	Nov 2010	60.2	NHDOT	CS	33.7	25	1	Fed Br	NPR Y		1929, 1993
State Redlist				Structurally Deficient	Over		2600, 2008	30.0	Rural Mjr. Collector		Primary-DOT Maintained			
Slab Poor.						Rehab	To be addressed by Bridge Maintenance				2011			

Nashua

1770

115/120	BALDWIN STREET	over	BMRR	Nov 2010	19.7	NHDOT	TB	13.0	73	3	Fed Br	06 Y	18.00	1935
State Redlist				Structurally Deficient	Over		1800, 2009	12.7	Urban Local		Compact Highway			
Low Capacity, Substructure Poor. Posted 'Weight Limit 6 Tons'. Was part of the Broad Street Parkway Project, Municipally Managed, estimated cost \$4684764.00. (To be bid 2005)						Replace	Waiting Municipal Action							

New Boston

1790

103/103	NH 13	over	S BR PISCATAQUOG RIVER	Nov 2010	31.8	NHDOT	CRF	31.3	62	1	Fed Br	NPR Y		1947
State Redlist				Structurally Deficient	Over		4600, 2009	23.9	Rural Mjr. Collector		Secondary-DOT Maintained			
Poor Condition.						Rehab	To be addressed by Bridge Maintenance				2011			

NHDOT Redlist Summary

Bridge Data --> Insp Date FSR Owner Type Width Length Spans Weight VC over/under Year Built
Road Data --> AADT, Year Status Width Functional Class NH System / Class & Rebuilt

Redlist Note

New Castle

1810

031/142	NH	1B	over	PISCATAQUA ESTUARY	Nov 2010	55.4	NHDOT	IB-C	34.3	484	9	Fed Br	NPR	Y	1955, 1987
				State Redlist	Structurally Deficient	Over		2700, 2006	28.0	Urban Minor Arterial	Primary-DOT Maintained				
				Substructure Poor. Piles with holes rusted through at bottom of pier caps.			Rehab	In the Program				\$1,695,806.00 2011			
066/071	NH	1B	over	LITTLE HARBOR	Mar 2011	14.2	NHDOT	BAS	30.8	253	6	Fed Br	15	Y	1942, 1975
				State Redlist	Structurally Deficient	Over		4300, 2007	24.0	Urban Minor Arterial	Primary-DOT Maintained				
				Pile Repair by Bridge Maintenance, Contract Paint in 2000, some holes in stringers. Pile repair project 2009 (\$1,558,700.00). Posting reduced to 'Weight Limit 15 Tons' March 23, 2011			Rehab	In the Program				\$11,024,000.00 2013			

Newfields

1830

130/083	NEW ROAD	over	BMRR	Nov 2010	34.9	NHDOT	TB	18.9	41	2	Fed Br	06	Y	17.92	1930, 1985
State Redlist				Structurally Deficient	Over	480, 2008	16.8	Rural Local	Municipal Highway						
Low Capacity, Posted 'Weight Limit 6 Tons'.				Waiting Municipal Action											

New Hampton

1840

240/104	SMITHS CROSSING	over	NHRR	Nov 2010 *	18.3	NHDOT	TB	16.0	82	3	Fed Br	06	Y	20.50	1940
		State Redlist		Structurally Deficient		Over	0, 2008		14.5	Rural Local		Unmaintained Highway			
		Deck Serious. Low Capacity, Posted 'Weight Limit 6 Tons'. Consider for removal.					Monitor and Keep in Service								

New Ipswich

1860

157/093	NH123,NH124	over	SOUHEGAN RIVER	Nov 2010	39.9	NHDOT	IB-C	30.2	135	9	Fed Br	E2	Y	1900, 1957
High Bridge			State Redlist	Structurally Deficient	Over		5400, 2008	24.0	Rural Mjr. Collector				Secondary-DOT Maintained	
			Poor Condition. Scour Critical.			Replace	In the Program				\$3,281,500.00	2012		

NHDOT Redlist Summary

Bridge Data --> Insp Date FSR Owner Type Width Length Spans Weight VC over/under Year Built
 Road Data --> AADT, Year Status Width Functional Class NH System / Class & Rebuilt

Redlist Note

Newton

1930

064/107	POND ROAD	over	BMRR	Nov 2010	42.9	NHDOT	TB	25.0	41	1	Fed Br	08	Y	17.58	1920, 2003
	State Redlist		Not Deficient	Over				590, 2008	20.9	Rural Local				Municipal Highway	
	Low Capacity, Posted 'Weight Limit 8 Tons'. Bridge Maintenance replaced deck and stringers, 2003.														Waiting Municipal Action

Northfield

1960

117/157	I-93 SB	over	NHRR,WINNIPESAUKEE RIVER	Nov 2010	52.6	NHDOT	IB-C	50.5	342	4	Fed Br	NPR	Y	20.90	1960, 1980
	State Redlist		Structurally Deficient	Over		NHS		13224, 2008	46.5	Rural Interstate				Interstate Highway	
	Deck Poor, Scour Critical					Rehab		In the Program						\$7,868,214.00	2014
118/158	I-93 NB	over	NHRR,WINNIPESAUKEE RIVER	Nov 2010	53.6	NHDOT	IB-C	42.5	333	4	Fed Br	NPR	Y	23.29	1960, 1980
	State Redlist		Structurally Deficient	Over		NHS		13224, 2008	40.0	Rural Interstate				Interstate Highway	
	Deck Poor, Scour Critical.					Rehab		In the Program						\$7,868,214.00	2014

North Hampton

1970

130/064	CEDAR ROAD	over	BMRR	Nov 2010	54.8	NHDOT	TB	21.0	34	1	Fed Br	11	Y	17.45	1920, 2002
	State Redlist		Not Deficient	Over				2200, 2005	19.0	Rural Local				Municipal Highway	
	Low Capacity, Posted 'Weight Limit 11 Tons'. Repairs by Bridge Maintenance 2002.														Waiting Municipal Action
148/132	US 1	over	BMRR	Nov 2010	34.3	NHDOT	CTB	42.3	42	1	Fed Br	E2	Y	22.70	1935
	State Redlist		Structurally Deficient	Over				16300, 1994	34.0	Rural Minor Arterial				Primary-DOT Maintained	
	Deck Poor.					Replace		Needs to be added to the						\$3,000,000.00	Program

Ossipee

2040

137/297	NH 16,NH 25	over	BEARCAMP RIVER	Nov 2010	11.4	NHDOT	IB-C	33.2	396	5	Fed Br	NPR	Y		1955
	State Redlist		Structurally Deficient	Over		NHS		11000, 2007	28.0	Rural Princ. Arterial				Primary-DOT Maintained	
	Superstructure Poor.					Replace		In the Program						\$4,500,000.00	2016

NHDOT Redlist Summary

Bridge Data --> Insp Date FSR Owner Type Width Length Spans Weight VC over/under Year Built
Road Data --> AADT, Year Status Width Functional Class NH System / Class & Rebuilt

Redlist Note

Ossipee

2040

137/299	NH 16,NH 25	over	RELIEF BEARCAMP RIVER	Nov 2010	32.4	NHDOT	IB-C	33.2	172	4	Fed Br	NPR Y	1955
	State Redlist		Structurally Deficient	Over		NHS	11000, 2007	28.0	Rural Princ. Arterial		Primary-DOT Maintained		
			Poor Deck and Substructure.			Replace	In the Program				\$3,000,000.00	2016	
152/268	NH 16,NH 25	over	LOVELL RIVER	Nov 2010	40.6	NHDOT	IB-C	34.5	62	1	Fed Br	C2 Y	1950
	State Redlist		Structurally Deficient	Over		NHS	11000, 2007	31.0	Rural Princ. Arterial		Primary-DOT Maintained		
			Deck Poor.			Replace	In the Program				\$1,500,000.00	2016	
232/121	NH 16	over	PINE RIVER	Nov 2010	64.3	NHDOT	CB	48.0	28	1	Fed Br	NPR Y	1976
	State Redlist		Structurally Deficient	Over		NHS	8100, 2007	44.0	Rural Princ. Arterial		Primary-DOT Maintained		
			Slab Poor.			Rehab	To be addressed by Bridge Maintenance					2012	

Pelham

2050

110/090	MAIN STREET	over	BEAVER BROOK	Nov 2010	16.0	NHDOT	MA	35.7	46	2	Fed Br	E2 Y	99.00	1900, 1929
	State Redlist		Structurally Deficient	Over			4700, 2009	29.9	Rural Local		Secondary-DOT Maintained			
			Monitor Stonework, Poor Condition, Scour Critical.			Replace	In the Program				\$2,225,000.00	2015		
111/090	MAIN STREET	over	BEAVER BROOK	Nov 2010 *	69.5	NHDOT	MP	.0	11	1		NPR Y		1988
	State Redlist		Not Applicable	Over			4700, 2009	29.7	Rural Local		Secondary-DOT Maintained			
			Poor Condition.			Replace	In the Program				\$250,000.00	2015		

Peterborough

2080

087/077	US202,NH101	over	CONTOOCOOK RIVER	Nov 2010	63.0	NHDOT	IB-C	43.8	195	3	Fed Br	NPR Y	1958
			State Redlist	Structurally Deficient	Over		14000, 2008	40.8	Rural Minor Arterial			Primary-DOT Maintained	
			Deck Poor.			Rehab	In the Program				\$4,456,000.00	2018	

110/115	NH136	over	BROOK	Nov 2010 *	53.0	NHDOT	MP-A	.0	10	1		NPR Y	1950
			State Redlist	Not Applicable	Over		3000, 2008	23.6	Rural Local			Primary-DOT Maintained	
			Serious Condition.			Rehab	To be addressed by Bridge Maintenance					WTP	

NHDOT Redlist Summary

Bridge Data --> Insp Date	FSR	Owner	Type	Width	Length	Spans	Weight	VC over/under	Year Built
Road Data -->		Action	AADT, Year Status	Width	Functional Class	NH System / Class	Year		& Rebuilt

Redlist Note

Pinkhams Grant

2095

069/080	PATROL SHED ROAD	over	STONY BROOK	Sep 2010 *	36.0	NHDOT	IB-W	20.5	23	1	NPR	Y	1945, 1996
	State Redlist		Not Applicable	Over			0, 2000	18.0	Rural Local		Undetermined / NA		
	Poor Deck. Steel plates in place.					Replace	To be addressed by Bridge Maintenance				2011		

Pittsburg

2100

099/034	MURPHY DAM ROAD	over	DAM SPILLWAY	Oct 2010	40.1	NHDES	BGB	20.5	38	1	Fed Br	15	Y	1938
	State Redlist		Structurally Deficient	Over			10, 2000	17.0	Rural Mjr. Collector		Municipal Highway			
	Low Capacity, Posted 'Weight Limit 15 Tons'.						Monitor and Keep in Service							

Plymouth

2160

117/143	NH 25,NH 3A	over	BAKER RIVER	Sep 2010	32.4	NHDOT	IB-C	49.7	259	3	Fed Br	NPR	Y	1968
	State Redlist		Structurally Deficient	Over			11000, 2007	44.0	Rural Minor Arterial		Primary-DOT Maintained			
	Deck Serious, Superstructure Poor.					Rehab	In the Program				\$2,164,712.00	2011		

Portsmouth

2170

173/071	US 1 SB	over	US 1 BYPASS	Nov 2010	35.8	NHDOT	IB-C	26.0	182	4	Fed Br	NPR	Y	14.80 1940
	State Redlist		Structurally Deficient	Over		NHS	5300, 2008	22.5	Urban Principal Arterial		Primary-DOT Maintained			
				Road Under		NHS	21000, 2004	-3.3	Urban Expressway		Turnpike, not Primary			
	Deck Serious, Substructure Poor.					Remove	In the Program				\$3,200,000.00	2012		

183/087	NH 33	over	US 1 BYPASS	Nov 2010	37.9	NHDOT	IB-C	30.1	123	4	Fed Br	NPR	Y	15.39 1940
	State Redlist		Structurally Deficient	Over		NHS	6200, 2006	23.8	Urban Minor Arterial		Primary-Compact Maint.			
				Road Under		NHS	21000, 2004	-3.3	Urban Expressway		Turnpike, not Primary			
	Deck Serious.					Replace	In the Program				\$2,500,000.00	2012		

188/097	ISLINGTON STREET	over	US 1 BYPASS	Nov 2010	26.0	NHDOT	IB-C	31.7	123	4	Fed Br	NPR	Y	15.29 1940
	State Redlist		Structurally Deficient	Over			6500, 2009	24.0	Urban Collector		Compact Highway			
				Road Under		NHS	23000, 2003	-3.3	Urban Expressway		Turnpike, not Primary			
	Deck Serious.					Replace	In the Program				\$2,500,000.00	2012		

NHDOT Redlist Summary

Bridge Data --> Insp Date FSR Owner Type Width Length Spans Weight VC over/under Year Built
Road Data --> AADT, Year Status Width Functional Class NH System / Class & Rebuilt

Redlist Note

Portsmouth

2170

205/116	WOODBURY AVENUE	over	US 1 BYPASS	Nov 2010	61.2	NHDOT	CRF	52.0	90	1	Fed Br	NPR Y	12.07	1950
	State Redlist		Structurally Deficient	Over				6100, 2007	40.0	Urban Minor Arterial		Primary-Compact Maint.		
				Road Under		NHS		14000, 2003	-3.3	Urban Expressway		Turnpike, not Primary		
	Poor Condition.					Replace	In the Program					\$3,300,000.00	2021	
211/114	STARK STREET	over	US 1 BYPASS	Nov 2010	48.6	NHDOT	IB-C	30.7	123	4	Fed Br	NPR Y	15.29	1940
	State Redlist		Structurally Deficient	Over				60, 2007	20.0	Urban Local		Compact Highway		
				Road Under		NHS		14000, 2004	-3.3	Urban Expressway		Turnpike, not Primary		
	Deck Poor.					Replace	In the Program					\$3,300,000.00	2021	
227/112	MAPLEWOOD AVENUE	over	US 1 BYPASS	Nov 2010	16.2	NHDOT	IB-C	30.1	161	4	Fed Br	NPR Y	15.29	1940
	State Redlist		Structurally Deficient	Over				10000, 2009	21.7	Urban Collector		Compact Highway		
				Road Under		NHS		14000, 2004	-3.3	Urban Expressway		Turnpike, not Primary		
	Deck Serious, Substructure Poor.					Rehab	In the Program					\$5,500,000.00	2012	
247/084	US 1	over	PISCATAQUA RIVER	Nov 2010	6.0	NHDOT	LIFT	29.0	1201	13	Fed Br	03 Y	17.67	1921, 1982
Memorial Bridge	State Redlist		Structurally Deficient	Over				11000, 2009	28.0	Urban Minor Arterial		Primary-DOT Maintained		
	Serious Condition. Partial Structural Repairs 2004. Partial counterweight rope replacement 2008. Rehab Bid 2008 - Design Bid Contract being developed					Rehab	In the Program					\$90,000,000.00	2012	
251/108	US 1 BYPASS	over	PISCATAQUA RIVER & RR	Nov 2010	5.0	Interstate Bridge Auth.	LIFT	36.0	2804	27	Fed Br	20 Y	16.08	16.70 1940, 1991
Sarah M. Long Bridge	State Redlist		Structurally Deficient	Over		NHS		15000, 2006	30.0	Urban Expressway		Turnpike, not Primary		
	Deck Poor. Permanent electrical repairs 2008. Included in Transportation needs study. May become Replacement?					Rehab	In the Program					\$90,000,000.00	2015	

Raymond

2190

083/154	DUDLEY ROAD	over	LAMPREY RIVER	Nov 2010	20.3	NHDOT	CS	21.0	52	2	Fed Br	106 Y		1914, 1972
	State Redlist		Structurally Deficient	Over				630, 2007	18.0	Rural Local		Secondary-DOT Maintained		
	Substructure in Serious condition. Wings Settled, Posted 'Weight Limit 10 Tons'. Scour Critical.						Monitor and Keep in Service							

NHDOT Redlist Summary

Bridge Data --> Insp Date FSR Owner Type Width Length Spans Weight VC over/under Year Built
Road Data --> AADT, Year Status Width Functional Class NH System / Class & Rebuilt

Redlist Note

Rochester

2220

109/090	NH 11 over US202,NH 16,SP TPK	Nov 2010	43.6	Turnpike Bureau, NHDOT	IB-C	48.0	198	4	Fed Br	NPR Y	16.01	1958
	State Redlist	Structurally Deficient	Over	NHS	21000, 2007	40.0	Urban Principal Arterial	Primary-DOT Maintained				
			Road Under		19000, 1994	39.4	Urban Minor Arterial	Primary-Turnpike Maint.				
	Deck Poor. CWIP.			Rehab	In the Program			\$4,900,000.00	2009			
117/088	US202,NH 16,SP TPK over TEN ROD ROAD	Nov 2010	25.6	Turnpike Bureau, NHDOT	IB-C	53.3	80	1	Fed Br	NPR Y	13.85	1957
	State Redlist	Structurally Deficient	Over	NHS	31000, 2007	47.5	Urban Principal Arterial	Primary-Turnpike Maint.				
	Poor Condition, CWIP.			Rehab	In the Program			\$2,331,139.00	2009			
128/089	US202,NH 16,SP TPK over NH202A	Nov 2010	56.3	Turnpike Bureau, NHDOT	CRF	46.8	57	1	Fed Br	NPR Y	14.34	1957
	State Redlist	Structurally Deficient	Over	NHS	27000, 2005	41.0	Urban Principal Arterial	Primary-Turnpike Maint.				
	Poor Condition, CWIP.			Replace	In the Program			\$12,000,000.00	2009			
139/094	NH 16,SP TPK over US202	Nov 2010	29.6	Turnpike Bureau, NHDOT	IB-C	53.3	67	1	Fed Br	NPR Y	15.75	1957
	State Redlist	Structurally Deficient	Over	NHS	27000, 2005	47.5	Urban Principal Arterial	Primary-Turnpike Maint.				
	Poor Condition, CWIP.			Rehab	In the Program			\$12,000,000.00	2009			

Rollinsford

2230

069/046	OAK STREET over BMRR	Nov 2010	21.0	NHDOT	LT	26.5	65	1	Fed Br	06 Y	17.67	1890, 1928
	State Redlist	Structurally Deficient	Over		7200, 2007	22.7	Urban Minor Arterial	Compact Highway				
	Posted 'Weight Limit 6 Tons'. Bridge Maintenance replaced all timbers 2007				Waiting Municipal Action							
116/086	NH 4 over SALMON FALLS RIVER	Nov 2010	60.3	NHDOT	IB-C	52.4	164	2	Fed Br	NPR Y		1970
	State Redlist	Structurally Deficient	Over		9700, 2005	44.7	Urban Minor Arterial	Primary-DOT Maintained				
	Deck Poor.			Rehab	In the Program			\$2,839,688.00	2011			

Rumney

2250

138/075	QUINCY ROAD over STINSON BROOK	Sep 2010	45.8	NHDOT	IB-C	32.3	46	1	Fed Br	C3 Y		1937
	State Redlist	Structurally Deficient	Over		810, 2007	25.3	Rural Min. Collector	Secondary-DOT Maintained				
	Poor Condition.			Rehab	To be addressed by Bridge Maintenance					2011		

NHDOT Redlist Summary

Bridge Data --> Insp Date	FSR	Owner	Type	Width	Length	Spans	Weight	VC over/under	Year Built
Road Data -->		Action	AADT, Year Status	Width	Functional Class	NH System / Class			& Rebuilt

Redlist Note

Salem

2280

058/089	BROOKDALE ROAD	over	I-93	Nov 2010	64.8	NHDOT	IB-C	38.5	207	2	Fed Br	NPR Y	16.40	1961
	State Redlist		Structurally Deficient	Over		NHS		940, 2007	30.0	Rural Local		Municipal Highway		
				Road Under		NHS		87000, 2003	-3.3	Rural Interstate		Interstate Highway		
	Deck Poor. CWIP.					Replace	In the Program					\$5,009,394.00	2010	
068/078	I-93 SB	over	NH 97(PELHAM ROAD)	Nov 2010	23.3	NHDOT	IB-C	47.8	127	3	Fed Br	NPR Y	15.49	1961
	State Redlist		Structurally Deficient	Over		NHS		41500, 2006	42.0	Rural Interstate		Interstate Highway		
	Serious Condition.					Replace	In the Program					\$23,450,000.00	2012	
070/079	I-93 NB	over	NH 97(PELHAM ROAD)	Nov 2010	27.6	NHDOT	IB-C	43.8	134	3	Fed Br	NPR Y	15.19	1961
	State Redlist		Structurally Deficient	Over		NHS		41500, 2006	38.0	Rural Interstate		Interstate Highway		
	Serious Condition.					Replace	In the Program					\$23,450,000.00	2012	
073/063	I-93 SB	over	NH 38	Nov 2010	25.6	NHDOT	IB-C	43.8	139	3	Fed Br	NPR Y	14.14	1961
	State Redlist		Structurally Deficient	Over		NHS		41500, 2006	38.0	Rural Interstate		Interstate Highway		
	Serious Condition. Also damaged by Roll Off delivery truck 2009.					Replace	In the Program					\$25,766,959.00	2011	
077/063	I-93 NB	over	NH 38	Nov 2010	26.6	NHDOT	IB-C	43.8	142	3	Fed Br	NPR Y	14.40	1961
	State Redlist		Structurally Deficient	Over		NHS		41500, 2006	38.0	Rural Interstate		Interstate Highway		
	Serious Condition.					Replace	In the Program					\$25,766,959.00	2011	

Sanbornton

2310

127/099	I-93 NB	over	SALMON BROOK	Nov 2010 *	58.0	NHDOT	CB	.0	28	1	Fed Br	NPR Y		1962
	State Redlist		Structurally Deficient	Over		NHS		11500, 2008	38.0	Rural Interstate		Interstate Highway		
	Culvert Poor in areas.					Rehab	In the Program					\$890,000.00	2018	

Sandown

2320

082/103	NH121A	over	EXETER RIVER	Mar 2011	39.4	NHDOT	CS	30.5	25	1	Fed Br	E2 Y		1937
	State Redlist		Structurally Deficient	Over				4100, 2007	27.0	Rural Mjr. Collector		Secondary-DOT Maintained		
	Poor Condition.					Rehab	To be addressed by Bridge Maintenance					2013		

NHDOT Redlist Summary

Bridge Data --> Insp Date FSR Owner Type Width Length Spans Weight VC over/under Year Built
 Road Data --> AADT, Year Status Width Functional Class NH System / Class & Rebuilt
 Redlist Note Action

Seabrook

2340

136/071	BMRR(ABD)	over	WALTON ROAD	Nov 2010	N/A	NHDOT	IB-W	10.0	24	1	Fed Br	NPR Y	12.47	1931
			State Redlist	Not Applicable	Road Under		3400, 2009	19.7	Rural Local			Secondary-DOT Maintained		
			Rail line not in service, Severe Overheight Damage, Poor Condition.		Remove		To be addressed by Rail and Transit					WTP		

Springfield

2390

091/048	GEORGES MILLS ROAD	over	STAR LAKE OUTLET	Nov 2010 *	70.0	NHDOT	MP	.0	12	2		NPR Y		1970
			State Redlist	Not Applicable	Over		500, 2008	52.0	Rural Local			Secondary-DOT Maintained		
			Culvert Poor. Runs diagonally across NH 114 through the four way intersection with Stryker Road and Fisher Corner Road.		Replace		Needs to be added to the Program							

Stewartstown

2410

054/163	BRIDGE STREET	over	CONNECTICUT RIVER	Oct 2010	14.2	NHDOT	SA	30.5	232	9	Fed Br	10 Y		1930, 1971
			State Redlist	Structurally Deficient	Over		1600, 2008	24.0	Rural Min. Collector			Secondary-DOT Maintained		
			Poor Condition, America's Most Beautiful Steel Bridge, 1935, Class C. Posted 'Weight Limit 10 tons'.		Rehab		In the Program				\$6,325,000.00	2015		
121/114	NH145	over	BISHOP BROOK	Oct 2010	9.8	NHDOT	IB-C	23.0	42	1	Fed Br	C2 Y		1940
			State Redlist	Structurally Deficient	Over		750, 2009	20.0	Rural Min. Collector			Secondary-DOT Maintained		
			Substructure in Serious Condition.		Replace		In the Program				\$1,800,000.00	2016		

Stoddard

2420

129/109	NH123	over	DEAD BROOK	Nov 2010 *	34.8	NHDOT	MP	.0	10	2		NPR Y		1972
			State Redlist	Not Applicable	Over		610, 2008	28.0	Rural Mjr. Collector			Secondary-DOT Maintained		
			Culvert Poor.		Replace		To be addressed by Bridge Maintenance					2011		

NHDOT Redlist Summary

Bridge Data --> Insp Date FSR Owner Type Width Length Spans Weight VC over/under Year Built
Road Data --> AADT, Year Status Width Functional Class NH System / Class & Rebuilt

Redlist Note

Sullivan

2460

093/061	NH 9	over	OTTER BROOK	Nov 2010	27.0	NHDOT	CTB	27.8	92	2	Fed Br	NPR Y	1932
		State Redlist	Structurally Deficient	Over		NHS	7100, 2008	25.3	Rural Princ. Arterial	Primary-DOT Maintained			
			Superstructure Poor. 2005 flood damage repaired. Scour Critical	Replace			In the Program		\$5,585,945.00	2017			

Swansey

2510

149/072	NH 32	over	MARTIN BROOK	Nov 2010	41.7	NHDOT	CS	23.7	27	1	Fed Br	E1 Y	1929
		State Redlist	Structurally Deficient	Over			2800, 2007	21.5	Rural Mjr. Collector	Secondary-DOT Maintained			
			Poor Condition.	Rehab			To be addressed by Bridge Maintenance			2012			
150/056	NH 32	over	MARTIN BROOK	Nov 2010	49.5	NHDOT	CS	25.0	16	1		NPR Y	1928, 1972
		State Redlist	Not Applicable	Over			2800, 2007	22.0	Rural Mjr. Collector	Secondary-DOT Maintained			
			Poor Condition.	Rehab			To be addressed by Bridge Maintenance			2011			
167/175	SWANZEY FACTORY RD	over	TROY BROOK	Nov 2010 *	72.7	NHDOT	MP	.0	12	1		NPR Y	1970
		State Redlist	Not Applicable	Over			2600, 2007	28.0	Rural Local	Secondary-DOT Maintained			
			Culvert Poor.	Rehab			To be addressed by Bridge Maintenance			2011			

Tamworth

2520

150/106	NH113	over	BEARCAMP RIVER	Nov 2010	34.6	NHDOT	IB-C	34.3	123	3	Fed Br	E1 Y	1955
		State Redlist	Structurally Deficient	Over			1800, 2007	28.0	Rural Mjr. Collector	Secondary-DOT Maintained			
			Poor Condition. Temporary repairs scheduled in 2011, by Bridge Maintenance.	Replace			In the Program		\$3,310,000.00	2018			

Temple

2530

094/114	NH101	over	BLOOD BROOK	Nov 2010	42.6	NHDOT	CS	51.0	24	1	Fed Br	NPR Y	1930
		State Redlist	Structurally Deficient	Over		NHS	7629, 2009	47.5	Rural Princ. Arterial	Primary-DOT Maintained			
			Poor Condition.	Rehab			To be addressed by Bridge Maintenance			2014			

NHDOT Redlist Summary

Bridge Data --> Insp Date	FSR	Owner	Type	Width	Length	Spans	Weight	VC over/under	Year Built
Road Data -->		Action	AADT, Year Status	Width	Functional Class	NH System / Class	Year		& Rebuilt

Redlist Note

Temple

2530

107/051	NH 45	over	MILLER GAMBLE BROOK	Nov 2010 *	69.9	NHDOT	MP	.0	13	1	NPR	Y	1968
			State Redlist	Not Applicable	Over			930, 2007	30.0	Rural Min. Collector		Secondary-DOT Maintained	
			Culvert Poor.			Rehab		To be addressed by Bridge Maintenance				WTP	

Thornton

2540

175/076	CROSS ROAD	over	PEMIGEWASSET RIVER	Sep 2010	57.4	NHDOT	IB-C	36.0	417	4	Fed Br	NPR	Y	1973
			State Redlist	Structurally Deficient	Over			770, 2007	28.0	Rural Local		Secondary-DOT Maintained		
			Thornton Memorial Bridge			Rehab		In the Program				\$2,662,891.00	2011	
			Deck Poor. CWIP											

Wakefield

2610

230/057	NH 16	over	BRANCH RIVER	Nov 2010	37.4	NHDOT	IB-C	47.5	52	1	Fed Br	NPR	Y	1959
			State Redlist	Structurally Deficient	Over	NHS		8300, 2009	44.9	Rural Princ. Arterial		Primary-DOT Maintained		
			Poor Deck and Abutments.			Rehab		To be addressed by Bridge Maintenance				2014		

Walpole

2620

062/052	BRIDGE STREET	over	CONNECTICUT RIVER	Nov 2010	2.0	NHDOT	CA	32.5	230	2	Fed Br	BRC	Y	1930, 1974
			State Redlist	Structurally Deficient	Over			6500, 2006	24.0	Rural Mjr. Collector		Primary-DOT Maintained		
			Vilas Bridge			Rehab		In the Program				\$3,596,156.00	2015	
			Serious Condition. Closed to traffic March 19, 2009.											

Warner

2630

254/180	NH127	over	WARNER RIVER	Nov 2010	51.4	NHDOT	IB-C	28.2	123	3	Fed Br	C2	Y	1937
			State Redlist	Structurally Deficient	Over			1500, 2009	25.1	Rural Mjr. Collector		Secondary-DOT Maintained		
			Deck Serious.			Replace		In the Program				\$2,271,000.00	2012	

NHDOT Redlist Summary

Bridge Data --> Insp Date FSR Owner Type Width Length Spans Weight VC over/under Year Built
Road Data --> AADT, Year Status Width Functional Class NH System / Class & Rebuilt

Warren

2640

102/092	NH 25C	over	BLACK BROOK	Sep 2010 *	51.0	NHDOT	MP	.0	11	1	NPR	Y	1971
			State Redlist	Not Applicable	Over		800, 2009	31.7	Rural Min. Collector				Secondary-DOT Maintained
			Culvert Serious.			Replace	To be addressed by Bridge Maintenance						2014

Wentworth

2690

146/090	NH 25,NH118	over	BAKER RIVER	Sep 2010	64.9	NHDOT	IB-C	44.0	204	3	Fed Br	NPR	Y	1960
			State Redlist	Structurally Deficient	Over		3600, 2007	40.0	Rural Minor Arterial					Primary-DOT Maintained
			Deck Poor.			Rehab	In the Program					\$4,200,000.00	2011	

Wilton

2770

129/126	NH 31	over	SOUHEGAN RIVER	Nov 2010	36.8	NHDOT	IB-C	38.5	80	1	Fed Br	NPR	Y	1971
			State Redlist	Structurally Deficient	Over		5000, 2007	30.0	Rural Mjr. Collector					Secondary-DOT Maintained
			Deck Serious.			Rehab	Needs to be added to the Program					\$2,750,000.00		

Winchester

2790

113/077	NH119	over	ASHUELOT RIVER	Nov 2010	65.7	NHDOT	IB-C	43.5	194	3	Fed Br	NPR	Y	1962
			State Redlist	Structurally Deficient	Over		3700, 2007	40.0	Rural Mjr. Collector					Primary-DOT Maintained
			Deck Serious. Bid October 14, 2010			Rehab	In the Program					\$1,736,616.00	2011	
137/121	NH 10	over	FOREST LAKE OUTLET	Nov 2010	46.6	NHDOT	CB	37.0	12	1	E2	Y		1900, 1974
			State Redlist	Not Applicable	Over		7200, 2007	34.0	Rural Minor Arterial					Primary-DOT Maintained
			Poor Condition.			Replace	Needs to be added to the Program					\$500,000.00		
152/181	NH 10	over	ASHUELOT RIVER	Nov 2010	21.3	NHDOT	IB-C	31.3	181	3	Fed Br	NPR	Y	1935
			State Redlist	Structurally Deficient	Over		6800, 2007	24.0	Rural Minor Arterial					Primary-DOT Maintained
			Serious Condition. Scour Critical.			Replace	In the Program					\$6,720,290.00	2012	

NHDOT Redlist Summary

Bridge Data --> Insp Date	FSR	Owner	Type	Width	Length	Spans	Weight	VC over/under	Year Built
Road Data -->		Action	AADT, Year Status	Width	Functional Class	NH System / Class	Year		& Rebuilt

Redlist Note

Windham

2800

134/101	I-93 SB over NH111	Nov 2010	47.2	NHDOT	IB-C	43.8	168	3	Fed Br	NPR Y	19.69	1961
---------	--------------------	----------	------	-------	------	------	-----	---	--------	-------	-------	------

State Redlist

Structurally Deficient Over

NHS

38500, 2006

38.0 Rural Interstate

Interstate Highway

Deck Serious. Substructure Poor. Anticipated traffic removal 2012, replacement bridge in 2014.

Replace

In the Program

\$4,000,000.00 2014

135/090	I-93 SB over NH111A	Nov 2010	63.8	NHDOT	IB-C	43.8	160	3	Fed Br	NPR Y	15.09	1961
---------	---------------------	----------	------	-------	------	------	-----	---	--------	-------	-------	------

State Redlist

Structurally Deficient Over

NHS

38500, 2006

38.0 Rural Interstate

Interstate Highway

Deck Serious. Anticipated traffic removal 2012, replacement bridge in 2014.

Replace

In the Program

\$4,000,000.00 2014

Total Bridge Count: 148